


May 2009

## Latest Software and Firmware for Construction

Last Updated: 12<sup>th</sup> May, 2009

For notices of updates to Software for firmware via [RSS](#) 

**Note:** Release dates are only included for software and firmware released since May 2004

Product	Software	Firmware	OS	Release date	Available from
<b>Site Positioning Systems</b>					
5600 (PVX)		696-03.08			Service Center
5700		2.32		May 2007	<a href="#">Trimble.com</a>
5800		2.32		May 2007	<a href="#">Trimble.com</a>
ATS (PVX4S E 00)		696-03.08	698-02.00		Service Center
ATS (PVX4S E 01)		796-03.08	798-02.00	October 2006	Service Center
DSM12/212		1.71			<a href="#">Trimble.com</a>
DSM132		3.00		October 2005	<a href="#">Trimble.com</a>
DSM232		3.62		November 2008	<a href="#">Trimble.com</a>
Geodimeter® CU new board		669-02.04			Service Center
Geodimeter® CU old board		632-11.04			Service Center
MS750™		1.58		September 2006	<a href="#">Trimble.com</a>
SPS700		C8.0.37		February 2009	<a href="#">Trimble.com</a>
SPSx10		C8.0.37		February 2009	<a href="#">Trimble.com</a>
SPSx30		C8.0.37		February 2009	<a href="#">Trimble.com</a>
SPS770		2.32		October 2008	<a href="#">Trimble.com</a>
SPS780		2.32		October 2008	<a href="#">Trimble.com</a>
SPS781		4.01		April 2009	<a href="#">Trimble.com</a>
SPSx5x		4.03		May 2009	<a href="#">Trimble.com</a>
SPSx61		4.03		May 2009	<a href="#">Trimble.com</a>
SPS88x		4.01		April 2009	<a href="#">Trimble.com</a>
ACU (SCS900, English)	2.33		4.0.12	March 2008	<a href="#">Trimble.com</a>
TCU (SCS900, English)	2.5		4.2.5.12/ 5.0.0.19	April 2009	<a href="#">Trimble.com</a>

Trimble Construction Division, 5475 Kellenburger Road, Dayton, OH 45424, USA

© XXXX, Trimble Navigation Limited. All rights reserved. Trimble, the Globe & Triangle logo, XXX, XXX, and XXX are trademarks of Trimble Navigation Limited, registered in the United States Patent and Trademark Office and in other countries. XXX, XXX, and XXX is a/are trademark/trademarks of Trimble Navigation Limited. All other trademarks are the property of their respective owners.



Product	Software	Firmware	OS	Release date	Available from
TSC2 (SCS900, English)	2.5		5.0.3	April 2009	<a href="http://Trimble.com">Trimble.com</a>
TSCe (SCS900, English)	2.33		4.0.12	March 2008	<a href="http://Trimble.com">Trimble.com</a>
Tablet (SCS900, English)	2.5		Windows XP/Vista	April 2009	<a href="http://Trimble.com">Trimble.com</a>
ACU (SCS900, Other Languages)	2.32		4.0.12	March 2008	<a href="http://Trimble.com">Trimble.com</a>
TCU (SCS900, Other Languages)	2.42		4.2.5.12/ 5.0.0.19	October 2008	<a href="http://Trimble.com">Trimble.com</a>
TSC2 (SCS900, Other Languages)	2.42		5.0.3	October 2008	<a href="http://Trimble.com">Trimble.com</a>
TSCe (SCS900, Other Languages)	2.32		4.0.12	March 2008	<a href="http://Trimble.com">Trimble.com</a>
<b>Layout Systems</b>					
LM80 V4.x	4.51		Mobile 6	March 2009	<a href="http://Trimble.com">Trimble.com</a>
LM80 V4.x	4.51		Mobile 5	March 2009	<a href="http://Trimble.com">Trimble.com</a>
LM80 V4.x	4.51		Pocket PC	March 2009	<a href="http://Trimble.com">Trimble.com</a>
LM80 V3.x	3.23		Mobile 5	April 2007	<a href="http://Trimble.com">Trimble.com</a>
LM80 V3.x	3.23		Pocket PC	April 2007	<a href="http://Trimble.com">Trimble.com</a>
LM80 Desktop	2.51			March 2009	<a href="http://Trimble.com">Trimble.com</a>
SPSx10		C8.0.37		February 2009	<a href="http://Trimble.com">Trimble.com</a>
SPSx30		C8.0.37		February 2009	<a href="http://Trimble.com">Trimble.com</a>
SPS700		C8.0.37		February 2009	<a href="http://Trimble.com">Trimble.com</a>
RTS Robotic Total Station Series		C8.0.37		February 2009	
<b>Radio Infrastructure Systems</b>					
TNR900		1.24		January 2008	<a href="http://Trimble.com">Trimble.com</a>
SNB900		2.10		February 2009	<a href="http://Trimble.com">Trimble.com</a>
Trimble PDL 450		2.42		February 2007	<a href="http://Trimble.com">Trimble.com</a>
TRIMMARK™ 3		1.30		February 2008	<a href="http://Trimble.com">Trimble.com</a>
TRIMTALK™ 450S			2.15		N/A
GeoRadio			626-06.07		Service Center
GeoRadio 2.4 GHz			626-08.02	December 2005	Service Center
<b>GCS Series Components</b>					
AS21		1.54	4.37		Dealer
AS400		3.04		Jan 2007	Dealer
AS450		1.1		March 2009	Dealer
AS460		1.1		March 2009	Dealer
CB410		1.10		May 2007	Dealer
CB420		2.51		October 2007	Dealer
CB430		11		February 2009	Dealer
CM310		1.04		April 2008	Service Center

Product	Software	Firmware	OS	Release date	Available from
EM400		1.86		October 2006	Dealer
LC450		1.1		March 2009	Dealer
LR400		1.83		November 2006	Dealer
LR410		1.88		November 2006	Dealer
MS980		1.4	1.10	March 2009	Dealer
MS990		3.81	3.21	March 2009	Dealer
MT900		1.1		March 2009	Dealer
RS400		1.89		October 2006	Dealer
SiteNet™ 450		1.28		October 2005	<a href="http://www.trimble.com">Trimble.com</a>
SR300		2.31		July 2007	Dealer
SNRx10		5.02		July 2008	
SNR900		3.18		February 2007	<a href="http://www.trimble.com">Trimble.com</a>
SNR2400		1.06		July 2006	Dealer
ST400		1.03		May 2007	Dealer
SV170 (GCS900)		6.11	2.12.021	October 2006	Dealer
VM410		1.74		December 2006	Dealer
VM415		1.00		April 2008	
VM420		1.87		July 2007	Dealer
<b>Paving Control System Components</b>					
CB440		1.00		February 2009	
<b>Office Software Products</b>					
Configuration Toolbox™	6.70			October 2007	<a href="http://www.trimble.com">Trimble.com</a>
DC File Editor	2.03				
Grid Factory	1.41				<a href="http://www.trimble.com">Trimble.com</a>
MS Controller™	1.1.0.0				
Paydirt® Roadwork	2.0.3				<a href="http://www.trimble.com">Trimble.com</a>
Paydirt Sitework	5.22			February 2004	<a href="http://www.trimble.com">Trimble.com</a>
Paydirt Trenchwork	2.00				
Planning	2.74				<a href="http://www.trimble.com">Trimble.com</a>
SiteVision Office	7.2			April 2009	Dealer

Product	Software	Firmware	OS	Release date	Available from
SCS Data Manager (English)	2.5			April 2009	<a href="http://Trimble.com">Trimble.com</a>
SCS Data Manager (Other Languages)	2.42			August 2008	<a href="http://Trimble.com">Trimble.com</a>
SCS Reporting Utility (English)	2.5			November 2008	<a href="http://Trimble.com">Trimble.com</a>
SCS Reporting Utility (Other Languages)	2.41			August 2008	<a href="http://Trimble.com">Trimble.com</a>
Terramodel®	10.61			April 2009	<a href="http://Trimble.com">Trimble.com</a>
Trimble Business Center- HCE	1.3			April 2009	<a href="http://Trimble.com">Trimble.com</a>
Trimble Exchange	2.3				
Trimble Office Synchronizer (English)	1.46			April 2009	<a href="http://Trimble.com">Trimble.com</a>
Trimble Office Synchronizer (Other Languages)	1.45			August 2008	<a href="http://Trimble.com">Trimble.com</a>
<b>Marine Construction Software</b>					
HYDRO <sup>pro</sup> ™	2.32			February 2008	
DSM Utility	1.03			April 2007	<a href="http://Trimble.com">Trimble.com</a>
<b>SiteVision® GPS Machine Control</b>					
AS21		1.54	4.37		Dealer
MS850™		1.58		September 2006	<a href="http://Trimble.com">Trimble.com</a>
MS860™		1.58		September 2006	<a href="http://Trimble.com">Trimble.com</a>
SiteNet™ 450		1.28		January 2005	<a href="http://Trimble.com">Trimble.com</a>
SiteNet™ 900		2.78		December 2006	<a href="http://Trimble.com">Trimble.com</a>
SV170 (SiteVision)		5.52	2.12.021	June 2005	Dealer
TRB		3.66			Dealer
<b>BladePro® Machine Control</b>					
0365-2040 Operator Interface Box		4.20			
0365-1140 Remote Box		6.70			
<b>BladePro® 3D Machine Control</b>					
0365-1140 Remote Box		6.70			
0366-2010 Graphical Operator Box	3.4C01	Loader 1.0C07	NT 4.01	Aug 04	
RTX		4.3.1			
System Softcard		5.2			

Product	Software	Firmware	OS	Release date	Available from
<b>ScreedPro® PA Control</b>					
CSM-30 Slope Module		4.3			
LM-25 Laser Interface Module		4.5			
R-25 Universal Remote		4.7			
ST2-25CE Sonic Tracer		4.5			